DEPT ON AGING

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		N105004	N105004		B. WING		03/13/2014	
NAME OF PROVIDER OR SUPPLIER			STREET ADDR	RESS, CITY, STA	TE, ZIP CODE	•		
002521121111002111211 25117115011222				51 BLAKE ST. DWARDSVILLE, KS 66111				
(X4) ID PREFIX TAG	SUMMARY ST (EACH DEFICIENC [*] REGULATORY OR L		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE		
S 000	S 000 INITIAL COMMENTS The following citations represent the findings of a Health Resurvey and Complaint Investigation #KS00073272.			S 000				
S1364 SS=F	26-40-305 (3) P E - Electrical requirements			S1364				
33 1	(3) Each electrical circuit to fixed or portable equipment in hydrotherapy units shall have a ground-fault circuit interrupter.							
	This Requirement is not met as evidenced by: The facility identified a census of 92 residents. Based on observation and interview the facility failed to maintain a safe, sanitary environment for residents on one of one halls of the facility.							
	Findings included:							
	- On 3-11-14 at 7:25 A.M. during the environmental tour, observation revealed the hydroculator (a thermostatically controlled water bath for warm moist packs applied to the body) in the therapy room was not plugged to a ground fault circuit interruption outlet (GFCI).							
	On 3-11-14 at approximately 7:30 A.M.maintenance staff Z acknowledged the hydroculator was not plugged into an GFCI outlet.							
	The facility failed to r for residents in the fa	maintain a safe, envirol cility.	nment					
I ARODATORY	DIRECTOR'S OR PROVIDER/	CLIDDI IED DEDDECENTATIVI	E'S SIGNATURE		TITLE		(X6) DATE	